Blosenski Landfill Route 340 West Caln Township, Chester County

ORIGINAL (Red)

File

103589

Mark A. Rosenberg Environmental Protection Specialist Region I - Norristown Office

A field inspection was conducted on April 23, 1976.

Current conditions on this property do not meet the with paragraph 4 of the Consent Order, C.A. 2004.

The only progress that has been noted since my has 1976, is that earthen material has been shalled as are a large number of tires. The nover material questionable.

The main problem at the site could be side sleed stabilization. There has been little or no effect side slopes as far as compacting and covering the side slopes into a wooded area at the morth

Inmediate concern is focused on the fact that different necest weeks, oil drums are being pierced and the substance, is spread over the fill area on the north site. A letter will be written to Mr. Blosenski to we accordingly.

MAR/mc/1m

200044

AT A STATE OF THE STATE OF THE